



Photo Documentation Report

Smith Residence

12489 Oak St N — Sioux Falls, SD 57104

Date: April 22, 2026

Claim # CLM-44271

17 photos

NOTES & COMMENTS

Hail damage was observed at 12489 Oak St N Sioux Falls, SD 57104, affecting the roof shingles, gutters and downspouts and roof flashing. Documentation of 17 photos confirms the damage is extensive, rendering the affected components beyond repair. Based on the scope and extent of the documented damage, full replacement of the affected components is recommended.



PHOTO 1 OF 17

Back Slope

Extensive hail damage was found to the shingles in the back slope test area.



PHOTO 2 OF 17

Back Slope

Extensive hail damage was found to the shingles in the back slope test area.



PHOTO 3 OF 17

Back Slope

Extensive hail damage was found to the shingles in the back slope test area.



PHOTO 4 OF 17

Back Slope

Extensive hail damage was found to the shingles in the back slope test area.



PHOTO 5 OF 17

Back Slope

Extensive hail damage was found to the shingles in the back slope test area.



PHOTO 6 OF 17

Back Slope

Extensive hail damage was found to the shingles in the back slope test area.



PHOTO 7 OF 17

Front Slope

Extensive hail damage was found to the shingles in the front slope test area.



PHOTO 8 OF 17

Front Slope

Extensive hail damage was found to the shingles in the front slope test area.



PHOTO 9 OF 17

Front Slope

Extensive hail damage was found to the shingles in the front slope test area.



PHOTO 10 OF 17

Front Slope

Extensive hail damage was found to the shingles in the front slope test area.



PHOTO 11 OF 17

Front Slope

Extensive hail damage was found to the shingles in the front slope test area.



PHOTO 12 OF 17

Front Slope

Extensive hail damage was found to the shingles in the front slope test area.



PHOTO 13 OF 17

Front Slope

Extensive hail damage was found to the shingles in the front slope test area.



PHOTO 14 OF 17

Roof Vents

Hail damage was noted to the metal roof vents.



PHOTO 15 OF 17

Roof Vents

Hail damage was noted to the metal roof vents.



PHOTO 16 OF 17

Chimney Flashing

Hail damage was noted to the chimney flashing.



PHOTO 17 OF 17

Chimney Flashing

Hail damage was noted to the chimney flashing.